

G7354005

FERGUSON

Customer Name: Ferguson	Date: 11/09/23
Customer Reference: 354005	Fitter: David H
Salesperson: Dave	Salesperson called: Yes/No Yes
Blind Type and number: Shutters	
Fault Description: Shutters for the bedrooms are too big Shutter for bathroom too small Lounge shutter doors don't line up with the windows and customer not happy with the size of them	
Action to correct:	
Problem fixed on site: Yes/No no	
Further action required: I've taken new sizes for the bedroom shutters to be cut down to if possible. Bathroom shutter needs remade at 1220 x 1030 Lounge shutter is up but customer wanting it remade bigger with doors lining up to window. Sizes on another sheet.	

Fault Report

Graeme unable to cut down - full refund.

Deposit paid - £1431.

COVER STRIPS


5x 90 x 20

5x 250 x 20

5x 1610 x 20

5x 1300 x 20

Lounge + side



H 1302
W-1611

+ H 1302
W 250

Baileys

14000 STEVENSON
 275 WASHINGTON
 DUBLIN, CA 94568
 TEL: 925 835 1100 FAX: 925 835 1101
 WWW.BAILEYS.COM

Customer's Name: **Ferguson**
 Address: **471 OAKFIELD WAY**
SEC 100

and condition

DATE: 2.5.12

Measured By: NAME

G35405

SPECIAL INSTRUCTIONS

Fit Random Room
 SIDE OF ROOM
 ALTERNATE BEING
 MADE BUT WON'T
 BE CO. FITTING

0136895611

Fitted By: DATE: DAY: AM/PM

Item	Width	Depth	Qty	Unit Price	Total Price	Notes
Harmon	1157	975	16	27.50	440.00	LR
Long Bed	1145	1152	16	31.25	500.00	LR
Diffuser Bed	1746	1135	16	47.62	762.00	LR
W	1153	1130	16	31.25	500.00	LR
Lunch	1610	1296	16	50.19	803.00	LR
	250	1296	16	7.75	124.00	R
60x120x1296				XL (corner)	30.00	
5 x 40x1296				X1 (corner)	20.00	
TOTAL					3181.00	
10% DISCOUNT					319.00	

✓ Rail	1220	1030
Plan Bed	1141	1145
RH Bed	1746	1130
LH Bed	1153	1121

PAID 2862.00
 RT 02/05/12
 VISA

PROV ACCEPTANCE Customer's Signature

ALL BLINDS TO
 BE PAID FOR
 AT TIME OF
 FITTING

BBAV