

G353917 / R
MURRAY.

Fault Report

Customer Name: Murray	Date: 27.04.23
Customer Reference: 353917	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Venetian, Blinds 1 & 2 bed bay	
Fault Description: Blinds measured incorrectly, both blinds should be 635mm width.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blinds.	