

G-353715
ROGERSON /
R1

Fault Report

Customer Name: Rogerson	Date: 27.04.23
Customer Reference: 353715	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Wood venetian, lounge	
Fault Description: Bind Measured incorrect width should be 1075mm Width x 1015mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new Blind, Customer £187 cheque and has agreed with the office that there is no more to pay. £63 discounted.	