

G 353878

BURT

Fault Report

Customer Name: Burt	Date: 27.04.23
Customer Reference: 353878	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Roller blind (motorised) bay 2	
Fault Description: Fabric damaged, 2 holes see images attached to email.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new roller, original motor can be swapped on site.	