

C 354016

WILSON-  
SMITH

# Fault Report

Customer Name: Wilson-Smith	Date: 16.06.23
Customer Reference: 354016	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Curtain Pole, Diner	
Fault Description: Customer has called office and said the curtain pole is incorrect. Pole was not fitted as there were no rings in the box. Curtain and pole left on site, all woods fitted no payment taken.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order correct pole with rings.  fitting new pole <u>4/7</u>	