

G353908
SINCLAIR

Fault Report

Customer Name: Sinclair	Date: 25.04.23
Customer Reference: 353908	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Vertical, Landing	
Fault Description: Customer not happy with slat drop, the drop on the recess is 1000mm and the slat size is 952mm leaving 11mm drop to the cill.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new slats at the correct size, other blinds in the property supplied and fitted by us are 5mm from the cill.	
Order slats @ 958mm	

Hem To
Hem.