

S354631

PEART

BAILEYS - S'MOOR

# Fault Report

Customer Name: PEART	Date: 24/04/23
Customer Reference: 354631	Fitter: SCOTT
Salesperson: SHAUN	Salesperson called: Yes/No YES
Blind Type and number: VERTICAL HEADRAIL	
Fault Description: HEADRAIL DAMAGED IN TRANSIT (DENTED) <del>REPLACE HEAD</del>	
Action to correct: REPLACE HEADRAIL 89mm WHITE - TOP FIX 4030 x 1990 1/R (54 CARRIERS) CTAL R - SPLIT BUNCH F/HT 2650 <hr/> SUPPLY 54 VANES ONLY (WELDED WTS) 1390 DROP 1/R FABRIC PERRIE MILK 89mm (OR PRICE ON ORIGINAL ORDER CHANGED TO ADD COST OF VANES)	
Problem fixed on site: Yes/No NO	
Further action required: REFIT NEW HEADRAIL & VANES.	