

G353735

REEVE

Fault Report

Customer Name: <i>reeve</i>	Date: <i>28/4/23</i>
Customer Reference: <i>353735</i>	Fitter: <i>CRAIG M</i>
Salesperson:	Salesperson called: Yes/No
Blind Type and number: <i>vertical headrail</i>	
Fault Description: <i>replace headrail must be 3017mm x 1560 conveys RS</i>	
Action to correct: <i>replace headrail at 3017mm x 1560 (RS)</i>	
Problem fixed on site: Yes/No	
Further action required:	