

S 354600

SIMPSON

Fault Report

Customer Name: SIMPSON	Date: 17/04/23
Customer Reference: 354600	Fitter: SCOTT
Salesperson: SHAUN	Salesperson called: Yes/No YES
Blind Type and number: 1x Roman	
Fault Description: EDGES ON BLIND ARE NOT STRAIGHT WRONG DROP - 10mm SHORTER THAN REQUESTED PHOTOS SENT	
Action to correct: REMAKE NEW BLIND 1705 x 1165 EX P/M 2300 LINARIA MOLESKIN BOUT LINING CHROME S' WINDER ON (R) SIDE	
Problem fixed on site: Yes/No NO	
Further action required:	