

G 353953

BELL.

Fault Report

Customer Name: Bell	Date: 17.05.23
Customer Reference: 353953	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Wood Venetian.	
Fault Description: All blinds should have 50mm slats not 25mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blind, all blinds have been temporarily fitted at customers request, please ensure this job is booked in for me(scott) as I will have been paid for this job.	