

G353978

ROBINSON

# Fault Report

Customer Name: Robinson	Date: 11.05.23
Customer Reference: 353978	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Roller, Kitchen	
Fault Description: Measured incorrectly, 1300mm width bracket to bracket. An after thought the width and the drop might have been wrote down in the wrong boxes but I never checked the drop when I was on site.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blind. Spoke to Scott - He said to make width + drop the same.	