

G353986

MATHIESON

# Fault Report

Customer Name: Mathieson	Date: 23.05.23
Customer Reference: <del>354004</del> 353986	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Roller, Blind 1 (Kitchen 1)	
Fault Description: Blind Measured incorrect size. Correct size is 1170mm width, size given is from bracket to bracket.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blind.  In. Unit to be collected.	