

S354781

STOCKTON

# Fault Report

Customer Name: Stockton	Date: 09.05.23
Customer Reference: 354781	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Pleated	
Fault Description: Customer not happy with coverage of blind width needs to be 560mm with 3mm extra fabric either side .	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Reorder blind.	