

Fault Report

Customer Name: HAYMAN	Date: 08-06-23
Customer Reference: 354 925	Fitter:
Salesperson: SHAUN H	Salesperson called: Yes/No
Blind Type and number: 1X ROLLER	
Fault Description:	
Action to correct: REDUCE WIDTH OF BLIND WIDTH 465 1/R	
Problem fixed on site: Yes/No	
Further action required:	