

5345762

RISE CARR

COLLEGE / R

Fault Report

Customer Name: Rise Carr Colledge	Date: 19.04.24
Customer Reference: 345762 <i>Commercial</i>	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Rollers	
Fault Description: 1 Roller has been pulled out the ceiling and 2 rollers need the chains joined and reattached to the wall.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: This need to be a 2 man fit with extension ladders. 2 hr job.	

Cost for 2 men (2 Hours)

£224

chain joiners + extension
ladders required