

S354896

SHUTTLEWORTH.

# Fault Report

Customer Name: SHUTTLEWORTH	Date: 30-05-23
Customer Reference: 345912	Fitter:
Salesperson: SHAUN H	Salesperson called: Yes/No YES
Blind Type and number: 1x VELUX B/O ROLLER	
Fault Description: BLIND HAS LOST TENSION & FABRIC HAS COME OUT OF SIDE CHANNELS AND WONT STAY UP	
Action to correct: REPLACE BLIND 1x B'OUT VELUX ROLLER DKL 1085 BEIGE GPL 308 3059 BLIND STILL UNDER VELUX GUARENTEE	
Problem fixed on site: Yes/No      NO	
Further action required:	

