

G 350133
MAYES / R

Fault Report

Customer Name: Mayes	Date: 05.07.23
Customer Reference: 350133	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes
Blind Type and number: Vertical headrail	
Fault Description: Measured incorrect and incorrect controls.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new headrail 1770mm right bunch right controls.	
<p>Customer has been <u>Refunded</u></p>	