

G350069
BARCLAY 1R

Fault Report

Customer Name: Barclay	Date: 05.06.23
Customer Reference: 350069	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Roller, Lounge 1 & 3	
Fault Description: Measured incorrectly, correct measurement for Blind 1 is 895mm Width.	
Action to correct: Used blind 1 for blind 3	
Problem fixed on site: Yes and No	
Further action required: Blind 1 (which was Blind 3) is in unit to be collected and cut down to 895mm (Recess size).	