

G 350109
KENT / R

Fault Report

Customer Name: KENT	Date: 27/06/23
Customer Reference: 350109	Fitter:
Salesperson: DAVE	Salesperson called: Yes/No
Blind Type and number: ROLLER	
Fault Description: REAR BEDROOM BLIND SHOULD HAVE BEEN BLACK OUT (BLIND AT UNIT) £90.00 BALANCE STILL TO PAY	
Action to correct: REMAKE AS A BLACKOUT BLIND	
Problem fixed on site: Yes/No	
Further action required:	