

G 350056
PEAREY 1/R

Fault Report

Customer Name: Pearey	Date: 16.06.23
Customer Reference: 350056	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes
Blind Type and number: All Blinds	
Fault Description: Motorised Visions need to be rolled from the front, Motorised romans were not motorised.	
Action to correct: Romans have been installed for customers privacy this was discussed with Graeme, the motors will be retro fitted on site by me and/or Graeme (I would need training on how to fit them first).	
Problem fixed on site: No	
Further action required: Order motorised components and collect visions to be altered. Please make this URGENT as customer has another big order waiting to go ahead.	