

G 350108  
THORESEN/R

# Fault Report

Customer Name: Thoreson	Date: 16.06.23
Customer Reference: 350108	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes
Blind Type and number: Roller, Kitchen	
Fault Description: Roller measured incorrectly, should be 5mm smaller to miss tiles.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new roller.	