

5354790

GRIFFITHS

Fault Report

Customer Name: Griffiths	Date: 27.06.23
Customer Reference: 354790	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: Yes
Blind Type and number: Curtain Poles	
Fault Description: No Rings or and gub screws missing from box.	
Action to correct: Use some spare rings (wrong colour) out the van to temporary install one pole.	
Problem fixed on site: No	
Further action required: Order 50no Rings to match poles, also order a load of gub screws for me to keep in the van. Second pole left on site.	
✓ Rings ordered @ Arora	
✓ Screws from Bayles Amazon.	