

G354046

CONSETT JUNIOR  
SCHOOL 1R

# Fault Report

Customer Name: Consett Junior		Date: 05/07/23
Customer Reference: 354046		Fitter: CRAIG M
Salesperson: Dave	Salesperson called: Yes/No	
Blind Type and number: rolls x 3		
Fault Description: remove roller NO ⑤ made wrong also cut down roller NO ① to 1685 mm and NO ② 1705 mm (measured wrong)		
Action to correct: cut down 2 x rollers NOS 1, 2 also remove NOS to correct spars		
Problem fixed on site: Yes/No		
Further action required:		