

G 350167
BEWERTON/R

Fault Report

Customer Name: BEWERTON	Date: 17/07/23
Customer Reference: 350167	Fitter: CRAIG
Salesperson: DAVE	Salesperson called: Yes/No
Blind Type and number: VENETIAN	
Fault Description: LOUNGE VENETIAN BLIND HAS BEEN MADE 10MM TOO WIDE, THE WIDTH SHOULD HAVE BEEN 950MM AS ORDERED BUT SUPPLIED AS 960MM CUSTOMER KEPT BACK £107.50 FROM BALANCE PAYMENT UNTIL SORTED.	
Action to correct: REMAKE BLIND 950MM WIDE	
Problem fixed on site: Yes/No	
Further action required:	