

G350201

REDPATH/R

Fault Report

Customer Name: Redpath	Date: 25.07.23
Customer Reference: 350201	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes
Blind Type and number: Verticals	
Fault Description: Headrails measured incorrectly Kitchen should be 1470mm, Rear bedroom should be 1960mm, Landing should be 965mm.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Remake headrails.	