

G:350055

SCOTT / R.

Customer Name: Scott	Date: 09/08/23
Customer Reference: 350055	Fitter: David
Salesperson:	Salesperson called: Yes/No
Blind Type and number: Shutters	
Fault Description: Previous shutter fitted screw hides have come off and needs more tape to put them back on. Also needs more grey caulk around shutter	
Action to correct:	
Problem fixed on site: Yes/No no	
Further action required: Needing booked in with double sided and grey caulk	

Fault Report

Shutter Survey Sheet

Number of Shutters: 1	Survey Date: 18-5-23	Customer Name: SCOTT	Filters Required:	
Survey Sheet: 1	Surveyor: DAVE	Order Number: 35055	Estimated Fit Time:	
Item Number: 1	2	3	4	5
Material: NEW YORK				
Colour: 880 SEAMIST				
Room Name: BEDROOM				
Width: 1155				
Drop: 985				
Mounting Type: BULK				
Panel Quantity: 2				
Louvre Size: 63				
Tilt Rod Type: COWHIT				
Mid Rail: NO				
Louvre Spelt: NO				
Panel Configuration: LA				
Hinge Colour: S STEEL				
Frame Type: 20.11614347164				
No of Sides: 4				
Stile Type: 155 413				
Build D-I: NO				
Extras: NO				
Further Instructions:				
Further Instructions:				

Material	83mm	76mm	89mm	114mm
New York	850/650	850/650	850/650	850/650
Los Angeles PVC	900/650	900/650	900/650	900/650
New York Max Config				
Los Angeles PVC Max Config				

Material	Y / N
New York	
Los Angeles PVC	
New York Max Config	
Los Angeles PVC Max Config	

Material	Length	Quantity
New York		
Los Angeles PVC		
New York Max Config		
Los Angeles PVC Max Config		

Order Information:

Balance to Pay:

Date:

Customer Signature:

Surveyor Signature: