

5348468

RUSSELL/R

Fault Report

Customer Name: Russell	Date: 06/07/23
Customer Reference: 348468	Fitter: CRAN
Salesperson: service call	Salesperson called: Yes/No
Blind Type and number: PIKE ROLLER	
Fault Description: replace pike roller to chain type as blind constantly pulls back up	
Action to correct: replace PIKE to chain type	
Problem fixed on site: Yes/No	
Further action required:	