

S354990

DAWSON

Fault Report

Customer Name: Dawson	Date: 14.08.23
Customer Reference: 354990	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Vertical	
Fault Description: Vertical curved track missing for living room Bay.	
Action to correct: I used the rear living room track for the living room bay as this was more important to have up.	
Problem fixed on site: No	
Further action required: As discussed with Graeme please order the rear living room track from the Middlesbrough manufacture and ill collect it and fit it on the same day..	