

G350329

MONOHAN /R.

# Fault Report

Customer Name: Monohan	Date: 16.08.23
Customer Reference: 350329	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes
Blind Type and number: Roller Con 1	
Fault Description: Measured incorrectly. Bracket to Bracket measures 2760mm	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Cut or remake roller.	