

# Fault Report

Customer Name: Early	Date: 17.08.23
Customer Reference: 350245	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes
Blind Type and number: Vertical, Kitchen	
Fault Description: Measured incorrectly. Kitchen should be 1965mm Recess.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: remake headrail.	



# VERTICAL BLINDS

## Order Form

Company / Shop: **BRILEY 3 / 20 STORM**

Sales Rep: **DAVE**

Date: **13/7/23**

Special Instructions:

Customer Name: **EARLY**

Order Reference: **350245**

BLIND SIZE & SYSTEM										CONTROLS				OPTIONS						
Loc-ation	Width (mm)	Drop (mm)	Recess (✓)	Exact (✓)	Child Safety/ Installation Height (mm)	Slot Size	Fabric Range	Fabric Colour	Slats only (✓)	RHS (✓)	LHS (✓)	Control Side (✓)	RHS (✓)	LHS (✓)	SPLIT (✓)	Wand Control	Headrail Colour	Fixing Brackets	Weight & Chained	
1	1990	1140	✓		2550	3 1/2	BOSTON FC	SILK				✓			✓	NO	WHITE	Tol	Nb	
2																				
3																				
4																				
5																				
6																				
7																				
8																				

**NOTE:** UNLESS OTHERWISE STATED ALL MEASUREMENTS WILL BE TAKEN AS RECES AND ALL OPTIONS WILL BE DEFAULT.

**FITTING NOTES:**