

G350321

BURN IR

COST BURN
TICKET 350321

Customer Name: Date: 29/8/23
Customer Reference: Fitter: SCOTT
Salesperson: Salesperson called: Yes/No Yes No DAVE

APARTMENT 17, LEVEL 5
MOOR COURT
408 FOLTON.
NE34YD

Blind Type and number: ROLLER ① + ②

0191-7242237

Fault Description: COST COMPLAINING ABOUT GAPS.

Action to correct:
DAVE HAS TURN CLOTH SO AS ROLL'S OFF THE FRONT REDUCING
GAPS A LOT,

Problem fixed on site: Yes/No No Yes

Further action required:

BLIND ① LH BRACKET + BLIND ② RH BRACKET NEEDS PULLING
DOWN AS TO MAKE GAP IN BLINDS EVEN.
1X STRIP OF CLOTH 3 1/2" WIDE AND 1700 LONG TO BE
SUPPLIED WITH FIT TO PIN TO WOOD BATTEN AT TOP SO TO
HIDE GAP A LITTLE BETTER, COST TO SUPPLY PINS TO ATTACH
AT TOP.

Fault Report

COST IS AWARE WILL STILL BE AND WILL ALWAYS BE
GAPS JUST TRYING TO HIDE THEM AS BEST AS POSSIBLE.
ALL ABOVE IS AGREED BY CUSTOMER

DAVE