

G350343

CRAIG / R,

CRAIG

Customer Name: Date: 12/9/23

Customer Reference/Fitter: SCOTT

Salesperson: Salesperson called: Yes/No

Blind Type and number: VERT N° ①

Fault Description:
GOES TO ONE SIDE + WANTED THE SPLIT BUNGW

Action to correct:
REPLACE HEADRILL + 1x LOUVER

Problem fixed on site: Yes/No

Further action required:

5100 BUNGW RT
1x NEW HEADRILL REQUIRED 1160x725 ZIR R/S 2150
WHITE INCOLOUR *1x LOUVER 725 ZIR DROP IN
3/12 FLORENCE WHITE *

Fault Report