

G349985
YHN 1R.

Fault Report

Customer Name: YHN	Date: 28.09.23
Customer Reference: 349985	Fitter: Scott Johnson
Salesperson: Dan	Salesperson called: No
Blind Type and number: Roller	
Fault Description: Stobbart house, kitchen roller should be 1600mm - <i>width</i> .	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new blind.	

