

G 355109

POTTS.

Fault Report

Customer Name: Potts	Date: 23.10.23
Customer Reference: 355109	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Vertical, Kitchen Roller 2 Porch	
Fault Description: Vertical slats are apparently shorted than she agreed with Dave. Roller 2 (775 x 1190) has a pin hole in the blackout material customer not aware.	
Action to correct: N/A.	
Problem fixed on site: No	
Further action required: Send Dave to discuss with customer about vertical slates. <i>Dave going back Mon 30/10.</i>	
Roller should be replaced but as above customer hasn't noticed the hole yet. <i>wait until customer calls regarding this.</i>	