

S356166
THOMPSON
IR

Fault Report

Customer Name: Thompson	Date: 06.10.23
Customer Reference: 356166	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Garden room, Venetian Blind 6	
Fault Description: Wand control mechanism snapped.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new mechanism to be fixed on site. See images attached to email.	