

①

②

Fault Report

Customer Name: Younger	Date: 25.09.23
Customer Reference: 356143	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Vertical, Rear Bedroom	
Fault Description: The 2 (5") vanes should be weld in weights. <i>* original order was weight & chain? → see Debbie</i>	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new vanes.	