

NAME BLEKE
TICKET 353635
30 TRIDENT DRIVE
BUTTA.

Customer Name: Date: 27/9/23

Customer Reference: Fitter: DAVID.

Salesperson: Salesperson called: Yes/No

Blind Type and number: SHUTTER (2)

Fault Description:

SHUTTER TOO BIG. CUST ALSO NOT HAPPY AT WAITING TIME, WAS DELAYED AS NO FITTER.

Action to correct:

REPLACE. MUST USE CORNER POSTS FROM ORIGINAL MEASURE.

Problem fixed on site: Yes/No

Further action required:

NEW SHUTTER TO BE ORDERED. GRAMAM SAID TO USE PVC. AS ONLY BE APPROX 4 WEEKS UNTIL FITTING. FOR THIS REASON ALL 3 SHUTTERS NEEDS TO BE ORDERED. NEW SIZES GIVEN TO GRAMAM VIA WHATS APP SO AS TO SPEED UP REPLACEMENT.

Fault Report

