

S356227

DONEGAN/R

# Fault Report

Customer Name: Donegan	Date: 25.10.23
Customer Reference: 356227	Fitter: Scott Johnson
Salesperson: Shaun Hanley	Salesperson called: No
Blind Type and number: Kitchen Door, Pleated	
Fault Description: Incorrect size fabricated.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Order new or adjust the pleated blind, finish size from top of headrail to bottom of bottom bar needs to be 1050mm exact this has been discussed with Graeme plus consult him before anything is done.	