

G355187

HARDESTY / R

Fault Report

Customer Name: Hardesty	Date: 08.11.23
Customer Reference: 355187	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Kitchen, Vertical	
Fault Description: Should be wand control	
Action to correct: N/A.	
Problem fixed on site: No	
Further action required: Order new headrail	