

S 354994

WALTON / R

Fault Report

Customer Name: WALTON	Date: 10-11-23
Customer Reference: 354994 WALTON	Fitter: GRAEME
Salesperson:	Salesperson called: Yes/No
Blind Type and number: PATIO SWITER.	
Fault Description: TRIM REQUIRED FOR ALONG THE TOP OF PATIO.	
Action to correct: ORDER TOP TRIM 25 30x4x 1018. RAL 7043	
Problem fixed on site: Yes/No	
Further action required:	