

9355153

Smyth/R.

Fault Report

Customer Name: Smyth	Date: 21.11.23
Customer Reference: 355153	Fitter: Scott Johnson/Dan
Salesperson: Dave	Salesperson called: No
Blind Type and number: Motorised Roller	
Fault Description: Blind 4 measured incorrectly.	
Action to correct: N/A.	
Problem fixed on site: No	
Further action required: Remake Blind @2195mm recess. 2 man fit on the return visit with large A-Frame ladder.	