

Invoice  
39538

# Fault Report

Customer Name: Danesmoor Group	Date: 30.11.23
Customer Reference: 355059	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: Yes
Blind Type and number: Motorised Rollers	
Fault Description: Rollers creasing loads when fully down.	
Action to correct: N/A.	
Problem fixed on site: No	
Further action required: Rollers to be collected and re-rolled on <del>45mm tubes</del> , two man job as discussed Benthin	

Scott collecting rollers  
04/11 AM.