

G350199  
DARRINGTON/R.

# Fault Report

Customer Name: DARRINGTON	Date: 8-12-23
Customer Reference: G350199	Fitter: GRAEME
Salesperson: DAVE	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number:	
Fault Description: SHAPE SHUTTER BOTTOM SLAT DAMAGED.	
Action to correct: NEED NEW BOTTOM SLAT OR NEW PANEL.	
Problem fixed on site: Yes/No	
Further action required:	