

ON100912R

G355341
SMYTH IR.

Fault Report

Customer Name: Smyth	Date: 21.12.23
Customer Reference: 355341	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Motorised rollers, Blind 4 & 5	
Fault Description: Blinds measured incorrectly.	
Action to correct: N/A.	
Problem fixed on site: No	
Further action required: Blinds are in the unit to be collected and the size altered. Blind 5 should be 1595mm and blind 4 should be 1610mm.	