

G355442  
MCDUGALL R

# Fault Report

Customer Name: MCDUGALL	Date: 24-5-24
Customer Reference: 355442	Fitter: GRAEME
Salesperson: DAVE	Salesperson called: Yes/No <input checked="" type="radio"/>
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number: LH REAR BED + OFFICE SHUTTER.	
Fault Description: PANELS DO NOT FOLD BACK DUE TO THE WAY THEY HAVE BEEN HINGED.	
Action to correct: RE NAME BOTH SHUTTERS.	
Problem fixed on site: Yes/No	
Further action required:	