

G355200

WAKEIR.

# Fault Report

Customer Name: WAKE	Date: 19-2-24
Customer Reference: 355200	Fitter:
Salesperson: DAVE	Salesperson called: Yes/No (No circled)
Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Blind Type and number:	
Fault Description: SLATS NOT TURNING ON DINER FIRST LEFT DOOR (DOOR 1)	
Action to correct: REMAKE DOOR 1.	
Problem fixed on site: Yes/No	
Further action required:	