

Fault Report

Customer Name: Snee	Date: 24.04.23
Customer Reference: 355757	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Roller (LH Rear Bedroom)	
Fault Description: Damage to blackout material.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Customer unaware. Speak to Graeme how he wants to deal with this.	