

G353362 /
BENTLEY / R.

Fault Report

Customer Name: Bentley	Date: 22.04.23
Customer Reference: 353362	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Motorised Roller Hall	
Fault Description: Motor not holding its charge.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: New Motor to be send and fitted.	