

G 355876

TAYLOR

Fault Report

Customer Name: Taylor	Date: 03.06.24
Customer Reference: 355876	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Vertical, Bedroom	
Fault Description: Headrail Fabricated incorrectly.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Debbie has images, remake headrail correct size. *Scott took wrong headrail * To go back and swap over.	