

355841

G355841

STEVENSON / R

Fault Report

ON101980R

Customer Name: Stevenson	Date: 24.05.24
Customer Reference: 355841	Fitter: Scott Johnson
Salesperson: Dave	Salesperson called: No
Blind Type and number: Roman	
Fault Description: incorrect size blind fabricated/ordered.	
Action to correct: N/A	
Problem fixed on site: No	
Further action required: Blind should be as top sheet 1840mm.	

ROMAN BLINDS

Order Form

Special Instructions

Date: 1/5/24

Order Reference: 355841

Sales Rep: DAVE

Customer Name: STEVENSON

Company / Shop: Brite's / Gas Farm

BLIND SIZE & SYSTEM										CONTROLS				OPTIONS			
Loc. Allocation	Width (mm)	Drop (mm)	Recess (✓)	Exact (✓)	Child Safety Installation Height (mm)	System Standard Clear/Deluxe	Fabric Range	Fabric Colour	Operation		Lining	Chain Colour	Lining	Pattern Match Day Position		Fixing	
									RHS (✓)	LHS (✓)				L/C/R	FACE (✓)		
1	2000	1840	✓		2800		SKYLER	SHADON	✓			CUSTOMER'S STANDARD			✓		
2																	
3																	
4																	
5																	
6																	
7																	
8																	

NOTE: UNLESS OTHERWISE STATED ALL MEASUREMENTS WILL BE TAKEN AS RECESS AND ALL OPTIONS WILL BE DEFAULT.

FITTING NOTES: